



# CUSTOMER SERVICE

## Customer information Nr. 005-2022

### DOCUMENT DATE

April 2022

### CHANGE DATE IN PRODUCTION

19th April 2022

### AFFECTED SKU OR RANGE


ALL BLUSODA HOT/ SELFIZZ 30 HOT - PICCOLA 15 HOT/ SELFIZZ 15 HOT with the following product codes:  
900705 - 900706 - 900761 - 900888 - 900890 - 900895 - 900897 - 901116 - 901117 - 901118 - 901119 - 901186 - 901279  
First Serial Number in production: 2204058863

**DETAILS:** Technical improvements

**REQUESTED BY:** Blupura

**REASON:** Ensure the correct operation of the non-pressurized hot boiler

**CHANGES PROPOSAL:** Introduction of 2 springs in correspondence with the hot water outlet pipes (dispensing pipe and vent pipe), ensuring the position of the pipe bend and avoiding kinks that could compromise the operation of the boiler.



### DRAWINGS AND SPARE PARTS LIST

No modification of the technical drawings.

No modification of the spare parts list.

The spring is available as spare part with code 130257.

File : \\srvsql\documenti\TEC\CUSTOMER CARE\COMUNICAZIONI CLIENTI MODIFICHE PRODOTTO

**Roberta Sassetti** - Customer Service&Quality Manager