

CUSTOMER SERVICE

Customer information Nr. 001-2023

DOCUMENT DATE

December 2022

EXPECTED CHANGE DATE IN PRODUCTION

QUARTER 1/2023

AFFECTED SKU OR RANGE

ALL BCC 230V and 115V
ALL BOX 30 230V and 115V
ALL WAVE 30 230V and 115V


DETAILS: Change of carbonator bowl 0,5 LT code 130010

REQUESTED BY: Blupura (PMT 62/2022)

REASON: Technical improvement for the function of the sparkling water system working with 0,5 LT carbonator bowl.

CHANGES PROPOSAL: Upgrade to a new carbonator bowl with a inlet water injection of 1,25 mm which increases the inlet flow rate.

FIRST SERIAL NUMBER: 2302004663



DRAWINGS AND SPARE PARTS LIST

Exploded view drawings do not change

Spare parts list changes with new part number code 130261

No price increase